



BOSCH

Разработано для жизни



1	2	3	4	5
1607031255	1607031250	1607031266	1607031256	1607031223
6	7	8	9	10
1607031227	1607031252	1607031260	1607031254	1607031236
11	12	13	14	15
1607031264	1607031265	1607031263	1607031259	1607031222

Перфоратор (GBH)		Отбойный молоток (GSH)		Угловая шлифмашина (GWS)	
GBH 11 DE	0 611 245 703, 708	GSB 20-2 RET	0 601 19B 903	GWS 1000	3 601 H21 003, 8R0
GBH 2-22 E	0 611 250 603, 608	GSB 20-2 RET	0 601 192 803, 868, 880, 890	GWS 1000	3 601 H28 400, 800
GBH 2-22 RE	0 611 250 708	GSB 21-2 RCT	3 601 A9C 700, 701	GWS 10-125	3 601 H21 000, 020, 800
GBH 2-22 S	0 611 250 003	GSB 21-2 RE	3 601 A9C 500, 501, 600, 601	GWS 10-125 C	0 601 803 703, 903
GBH 2-23 RE	3 611 B50 400	GSB 450 RE	0 601 149 703, 708	GWS 10-125 C	0 601 702 703, 708, 773, 903
GBH 2-23 REA	3 611 B50 500	GSB 680 PROFI	0 601 184 351	GWS 10-125 C	0 601 802 503, 508
GBH 2-24 DFR	3 611 B73 000	GSB 780-2 RE	3 601 A7B 101	GWS 10-125 CE	0 601 383 703
GBH 2-24D	3 611 BA0 000	GSB 13	3 601 B17 092	GWS 10-125 CE	3 611 C21 000
GBH 2-24DF	3 611 BA0 100	GSB 13 RE	3 601 B17 100, 101, 102, 105, 106, 107	GWS 10-125 CE	0 611 318 703, 708
GBH 2-25 DV	3 611 B67 103	Отбойный молоток (GSH)		GWS 10-125 Z	3 601 H32 000
GBH 2-26 DBR	0 611 255 503	GSH 11 E	0 611 316 703, 708, 796	GWS 10-125C	0 601 802 573, 574, 703, 708, 773
GBH 2-26 DFR	0 611 254 703, 708	GSH 16-28	3 611 C35 000	GWS 10-125CE	0 601 803 773
GBH 2-26 DRE	0 611 253 703, 708	GSH 16-30	3 611 C35 100	GWS 11-125	3 601 G92 000, 0R0
GBH 2-26 E	0 611 251 603	GSH 5 CE	3 611 C21 000	GWS 11-125	3 601 G9D 000
GBH 2-26 RE	0 611 251 703, 708	GSH 5 E	0 611 318 703, 708	GWS 11-125 CI	3 601 H22 000, 020
GBH 2-28	3 611 B67 500	Угловая шлифмашина (GWS)		GWS 11-125 CIE	3 601 H23 000, 020
GBH 2-28 F	3 611 B67 600	GWS 1000	3 601 H21 003, 8R0	GWS 11-125 CIH	3 601 H30 100, 120, B00
GBH 2400	0 611 253 803	GWS 1000	3 601 H28 400, 800	GWS 11-125 P	3 601 G92 200
GBH 2600	0 611 254 803	GWS 10-125	3 601 H21 000, 020, 800	GWS 12-125	3 601 G93 000
GBH 3-28 DFR	3 611 B4A 000	GWS 10-125 C	0 601 803 703, 903	GWS 12-125 CIE	3 601 G94 000
GBH 3-28 DRE	3 611 B3A 000	GWS 10-125 C	0 601 702 703, 708, 773, 903	GWS 12-125 CIEP	3 601 G94 200
GBH 5-40 DCE	3 611 B64 000, 001	GWS 10-125 C	0 601 802 503, 508	GWS 12-125 CIEPX	3 601 G94 300
GBH 5-40 DE	0 611 241 703, 708	GWS 10-125 CE	0 601 383 703	GWS 12-125 CIEX	3 601 G94 100
GBH 7 DE	0 611 235 703, 708	GWS 10-125 CE	3 611 C21 000	GWS 12-125 CIP	3 601 G93 200
GBH 7-45 DE	0 611 235 803, 808	GWS 10-125 CE	0 611 318 703, 708	GWS 12-125 CIPX	3 601 G93 300
GBH 7-46 DE	0 611 263 703, 708	GWS 10-125 CE	0 601 803 503, 508, 573, 574, 575, 703, 708	GWS 12-125 CIX	3 601 G93 100
Шлифмашина по бетону (GBR)		GWS 10-125 Z	3 601 H32 000	GWS 13-125 CI	3 601 G93 0R0
GBR 15 CA	3 601 G76 000	GWS 10-125C	0 601 802 573, 574, 703, 708, 773	GWS 13-125 CI	3 601 G9E 000
Эксцентриксовая шлифмашина (GEX)		GWS 10-125 CE	0 601 803 503, 508, 573, 574, 575, 703, 708	GWS 13-125 CIE	3 601 G94 0R0
GEX 150 TURBO	0 601 250 703, 772, 791	GWS 10-125 CE	0 601 803 773	GWS 13-125 CIE	3 601 G9F 000
Прямая шлифмашина (GGS)		GWS 10-125CE	0 601 803 773	GWS 13-125 CIEX	3 601 G9F 100
GGS 28 C	3 601 B20 000	GWS 11-125	3 601 G92 000, 0R0	GWS 13-125 CIEX	3 601 G9E 100
GGS 28 CE	3 601 B20 100	GWS 11-125	3 601 G9D 000	GWS 14-125 C	0 601 H24 800, 830, 8R0
GGS 28 LC	3 601 B21 000	GWS 11-125 CI	3 601 H22 000, 020	GWS 14-125 CE	0 601 705 703, 708
GGS 28 LCE	3 601 B21 100	GWS 11-125 CIE	3 601 H23 000, 020	GWS 14-125 CE	3 601 H24 000, 020
GGS 28 LP	3 601 B25 000	GWS 11-125 CIH	3 601 H30 100, 120, B00	GWS 14-125 CIE	3 601 H25 000, 020
GGS 8 CE	3 601 B22 100	GWS 11-125 P	3 601 G92 200	GWS 14-125 CIT	3 601 H29 000, 020, A00, A30
Дисковая циркулярная пила (GKS)		GWS 12-125	3 601 G93 000	GWS 14-125 INOX	3 601 H29 J00
GKS 160	3 601 F70 000, 002	GWS 12-125 CIE	3 601 G94 000	GWS 14-125C	0 601 804 503, 508, 573, 574, 703, 708, 773
GKS 55	3 601 F64 000	GWS 12-125 CIEP	3 601 G94 200	GWS 14-125CE	0 601 805 503, 508, 573, 574, 703, 708, 773
GKS 55	3 601 F64 001	GWS 12-125 CIEPX	3 601 G94 300	GWS 14-150 C	0 601 706 703
Штроборез (GNF)		GWS 12-125 CIEX	3 601 G94 100	GWS 14-150 CI	3 601 H26 000, 020
GNF 65 A	0 601 368 703, 708	GWS 12-125 CIP	3 601 G93 200	GWS 14-150C	0 601 806 503, 573, 574
GNF 35 CA	0 601 621 703, 708	GWS 12-125 CIPX	3 601 G93 300	GWS 14-150C	0 601 806 703, 708, 732, 773
Универсальный резак (GOP)		GWS 12-125 CIX	3 601 G93 100		
GOP 2000 CE	3 601 B30 001	GWS 13-125 CI	3 601 G93 0R0		
GOP 250 CE	3 601 B30 000	GWS 13-125 CI	3 601 G9E 000		
GOP 30-28	3 601 B37 000	GWS 13-125 CIE	3 601 G94 0R0		
Поліровальная машина (GPO)		GWS 13-125 CIE	3 601 G9F 000		
GPO 14 CE	3 601 C89 000	GWS 13-125 CIEX	3 601 G9F 100		
Ударная дрель (GSB)		GWS 13-125 CIEX	3 601 G9F 100		
GSB 16 RE	3 601 A4E 500, 530, 600	GWS 13-125 CIE	3 601 G9E 100		
GSB 18	0 601 195 003	GWS 1400	3 601 H24 800, 830, 8R0		
GSB 18 RE	0 601 195 703	GWS 14-125 C	0 601 704 703, 708, 903		
GSB 18-2	0 601 185 003	GWS 14-125 CE	0 601 705 703, 708		
GSB 18-2 E	0 601 180 703	GWS 14-125 CI	3 601 H24 000, 020		
GSB 18-2 E	0 601 185 703	GWS 14-125 CIE	3 601 H25 000, 020		
GSB 18-2 RE	3 601 AA2 200	GWS 14-125 CIT	3 601 H29 000, 020, A00, A30		
GSB 18-2 RE	0 601 185 503	GWS 14-125 INOX	3 601 H29 J00		
GSB 19-2 RE	3 601 A7B 500, 600	GWS 14-125C	0 601 804 503, 508, 573, 574, 703, 708, 773		
GSB 19-2 REA	3 601 A7C 500	GWS 14-125CE	0 601 805 503, 508, 573, 574, 703, 708, 773		
GSB 20-2	0 601 19B 003	GWS 14-150 C	0 601 706 703		
GSB 20-2	0 601 184 003	GWS 14-150 CI	3 601 H26 000, 020		
GSB 20-2 RCE	0 601 19B 703	GWS 14-150C	0 601 806 503, 573, 574		
GSB 20-2 RCE	0 601 192 703, 708, 770	GWS 14-150C	0 601 806 703, 708, 732, 773		
GSB 20-2 RE	0 601 19B 403, 503				
GSB 20-2 RE	0 601 194 703, 708, 775, 790, 795				
GWS 15-125 CI	3 601 G95 000				
GWS 15-125 CIE	3 601 G96 000				
GWS 15-125 CIEH	3 601 H30 300, 320, D00				
GWS 15-125 CIEP	3 601 G96 200				
GWS 15-125 CIEX	3 601 G96 100				
GWS 15-125 CIH	3 601 H30 200, 220, C00				
GWS 15-125 CIP	3 601 G95 200				
GWS 15-125 CIPX	3 601 G95 300, 340				
GWS 15-125 CIT	3 601 G97 000				
GWS 15-125 CITH	3 601 H30 400, 420, 700, G00				
GWS 15-125 CIX	3 601 G95 100				
GWS 15-125 Inox	3 601 G9X 000				
GWS 15-150 CI	3 601 G98 000				
GWS 15-150 CIH	3 601 H30 500, 520				
GWS 15-150 CIP	3 601 G98 200				
GWS 17-125 CIE	3 601 G96 0R0				
GWS 17-125 CIE	3 601 G9H 000				
GWS 17-125 CIEH	3 601 G9H 100				
GWS 17-125 CIT	3 601 G97 0R0				
GWS 17-125 CIT	3 601 G9J 000				
GWS 17-125 CIX	3 601 G9G 100				
GWS 17-125 INOX	3 601 G9M 000				
GWS 17-150 CI	3 601 G98 0R0				
GWS 17-150 CI	3 601 G9K 000				
GWS 19-125 CI	3 601 G9N 000				
GWS 19-125 CIE	3 601 G9P 000				
GWS 19-125 CIST	3 601 G9S 000				
GWS 19-150 CI	3 601 G9R 000				
GWS 19-180	0 601 351 103, 108, 803				
GWS 19-230	0 601 352 103, 108, 803				
GWS 20-180	0 601 356 003, 903				
GWS 20-180	0 601 751 003, 008, 013, 020				
GWS 20-180 H	0 601 849 003				
GWS 20-180 H	3 601 H49 L03				
GWS 20-180 J	0 601 751 913				
GWS 20-180 JH	0 601 849 903				
GWS 20-230	0 601 752 003, 008, 013				
GWS 20-230	0 601 850 193				
GWS 20-230 H	0 601 850 003, 065, 103, 108				
GWS 20-230 J	0 601 752 903, 908, 913, 965				
GWS 20-230 JH	0 601 850 903, 908				
GWS 20-230H	3 601 H50 101, 102, L00, L01, L02				
GWS 20-230JH	3 601 H50 M00, M01				
GWS 21-180	0 601 356 103, 803				
GWS 21-180 H	0 601 851 003, 008, 083, 0A3, 0L4				
GWS 21-180 H	3 601 H51 L03				
GWS 21-180 HV	0 601 851 B03, B08				
GWS 21-180 JH	0 601 851 903, 908				
GWS 21-180 JHV	0 601 851 G03, G08, G18				
GWS 21-230	0 601 357 103, 188, 803				
GWS 21-230 H	0 601 852 003, 008, 083, 0A3				
GWS 21-230 H	3 601 H52 L02				
GWS 21-230 HV	0 601 852 B03, B08				
GWS 21-230 JH	0 601 852 903, 908				
GWS 21-230 JHV	0 601 852 G03, G08				
GWS 22-180 H	3 601 H81 100, 101, L00, L01, L02, Y00, Y01				
GWS 22-180 JH	3 601 H81 M00, M01, M02, Z00, Z01				

